Approved For Release 2001/03/05 : CIA-RDP82-00457R006100380003-4 25X1A E CHIAINES. DATE OF CONTENT. 25X1X DATE PREPARED 0 C-tober 1050 DATE OBTAINED. 25X1A REFERENCES PAGES 1 ENCLOSURES (NO. & TYPE) REMARKS\_\_\_\_ 25X1X SOURCE 1. The Gdynia-Babiedoly (C 55/Y 45) airfield was surrounded by a restricted area of approximately 4x6 km. The I Dn of the 3rd Polish AF Engr Regt (CO Polish soldiers, 430 P.Ts and LO women) was assigned to construction work at the field. 2. There was an M. runway, about Cox1,800 meters, and a SI-NA runway, 80x1,600 meters. Both runways had a concrete base, S to 10 cm thick and an asphilt surface of 3 cm. A concrete parking site of 100x200 meters was in front of the hangars. From this parking site a concrete taxiway about 30 meters wide ran to the eastern side of the Thi runway and to the south end of the SD-MI runway. Another taxiway, about 20 meters wide, paralleled the 7.5 runway and had several connecting lanes. 3. The following buildings and installations were at the field: Three hangars, one of which had been dismantled at the Langenau airfield near Breslau (P 52/C 52) in the fall of 1947; several wooden and stone buildings and workshops; and a flight control station with a weather station, a mobile DF station. The lighting facilities were still destroyed in February 1945 but it was observed that cables were hauled to the field, \* Comment. Confirms previous statements on the field and its installations. Nore recent statements on the occupation of the field have been received. See | 25X1A 25X1A Document Ko. ... No Change In Cia... 🗙 | Beclassified Class. Changed To: TS S C Auth .: HR 70-2 By: 034 Date: 270678

CONFIDENTIAL/CONTROL/US OFFICIALS ONLY

CLASSIFICATION.